Inspection Report

Name of Work	:	Repairs of Reading Room at BEL 6th Block in Ward No. 09, Vidyaranyapura Sub Division.
Work Order	:	EE/BTP/BBMP/KRIDL/WO/65/2014-15 Dated: 01.08.2014.
Agency	:	Technical Managar, KRIDL
B.R. No & Date	:	307/2014-15 Dated: 30.08.2014
Bill Amount	:	4,99,537.33
Job Code	:	009-14-000052
P. Code	:	P-1771
Date of Inspection	:	19-09-14

The above said Work Repairs of Reading at B.E.L 6th Block in Ward No. 09 Vidyaranyapura has been - Done by the Concerned. The above said Work has been inspected along with the Concerned.

The Measurements are Checked by me and Found Satisfactory.

The Work Done is Satisfactory

G.M.MUNIYAPPA,
B.E.(ELECTRICAL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Repair of Reading Room at BEL 6th Block in Ward No. 09 Vidyaranyapura Sub Division



Verified

G.M.MUNIYAPPA
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Assistant Engineer
WardNo. 09

Photos Showing the Work of Repairs of Reading Room at BEL 6th Block in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA,
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER(RTP)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Repairs of Reading Room at BEL 6th Block in Ward No. 09, Vidyaranyapura Sub Division.

Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA
B.E.(ELECT),B.E.(CIVIL)
EXECUTIVE ENGINEER(RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Repairs of Reading Room at BEL 6th Block in Ward No. 09, Vidyaranyapura Sub Division.





Assistant Engineer
Ward No. 09

G.M.MUNIYAPPA
B.E (ELECT),B.E (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Photos Showing the Work of Repairs of Reading Room at BEL 6th Block in Ward No. 09, Vidyaranyapura Sub Division.

G.M.N...
B.E.(ELECT),B.E. (CIVIL)
EXECUTIVE ENGINEER
PUBLIC WORKS DEPARTMENT

Assistant Engineer
Ward No. 09